40103 Flooring & Tiling

PAYROLL

2025 PAYROLL	PAYROLL PERCENTAGE OF CLASSIFICATIONS	2025 REBATE	PROPORTION OF PAYROLL CERTIFIED
$46.3M	2%	$39.7K	25%

SEVERE INJURIES

2023	2024	2025
9	8	10

TIMELOSS INJURIES

2023	2024	2025
20	18	28

RATE RISK CATEGORY

150%

TOP THREE INJURIES

PRIMARY CAUSE OF THE INJURY	PRIMARY SOURCE OF THE INJURY	NATURE OF THE INJURY	BODY PART INJURED
1. Overexertion in lifting	1. Bodily motion or position of worker	1. Sprains, strains, tears	1. Lumbar region
2. Struck by object	2. Boxes, crates, cartons	2. Fractures, dislocations	2. Knees
3. Bending, crawling, climbing	3. Table saw	3. Open wounds	3. Fingers

CSAM
CONSTRUCTION SAFETY ASSOCIATION OF MANITOBA

40103 Flooring & Tiling

This classification saw minor payroll growth in 2025 to 2% or currently $46.3 M.

Time Loss and Severe Injuries have increased within the non-certified work environment. 3 of the 10 Severe Injuries were in the non-certified environment. 25% of this workforce is safety- certified.

Claims Costs within the classification have remained steady and are reflective of Risk Category 150%. No changes are anticipated in the immediate future.

Please refer to the cover page to identify the top 3 drivers of Severe Injuries in the classification.

Sub-Group 401-03, Flooring & Tiling

Industry Sector 4: Construction

Rate Risk Category	150%

Included	Similar but Classified Elsewhere
✓ Installation and repair of flooring materials, including: • Hardwoods • Cork • Laminate • Linoleum • Vinyl sheet goods or tile • Ceramic or stone tile • Terrazzo • Carpet Includes sanding and refinishing existing or new hardwood flooring.	✘ Retail sales of flooring is found under 601-05, "Department Stores". ✘ Pouring concrete floors in basements if found under 401-10, "Concrete Work". ✘ Carpentry , masonry and general contracting are found under 401-02, "Building Construction".
✓ Tile-setting - the installation of ceramic, mosaic, quarry, marble or granite tiles on any surface, including the application of grout.	✘ Bricklaying is found under 401-02, "Building Construction".
✓ The installation of acoustic ceiling tile, suspended on a track or applied directly to the ceiling.	✘ Installing drywall to a ceiling is found under 401-08, "Drywall & Stucco Contracting".
✓ All resurfacing (leveling, removing prior coated surface), polishing and finishing of cement floors. Includes resurfacing through the use of any mechanical equipment or chemical means.	Cutting or repairing below the surface of the cement floor is found under 401-10, "Concrete Work".

Last Updated : January 4, 2022

DISCLAIMER: *Industry classification descriptions can change from time to time. Please make sure that you are reading the most current description, which can be found at www.wcb.mb.ca.*