40403 Roofing & Eavestroughing

PAYROLL

2025 PAYROLL	PAYROLL PERCENTAGE OF CLASSIFICATIONS	2025 REBATE	PROPORTION OF PAYROLL CERTIFIED
$105.6M	4%	$379.6K	69%

SEVERE INJURIES

2023	2024	2025
19	26	32

TIMELOSS INJURIES

2023	2024	2025
74	90	110

RATE RISK CATEGORY

500%

TOP THREE INJURIES

PRIMARY CAUSE OF THE INJURY	PRIMARY SOURCE OF THE INJURY	NATURE OF THE INJURY	BODY PART INJURED
1. Fall from ladder	1. Dislocation	1. Ground	1. Multiple body parts
2. Fall to floor / walkway	2. Sprains, strains, tears	2. Bodily motion / position	2. Fingers
3. Fall from roof edge	3. Open wounds	3. Floors, walkways	3. Knees

CSAM
CONSTRUCTION SAFETY ASSOCIATION OF MANITOBA

40403 Roofing & Eavestroughing

This classification saw a slight increase in payroll reported at $105.6 M. Approximately 69% of this payroll is safety certified.

In 2025, there was a significant increase to Severe Injuries and Time Loss claims. The classification had seen trending claims costs downward which would have reduced their Risk Category from 500% to 400%, within the next year or two.

Please refer to the cover page which will provide some insight into the causes and types of injuries sustained in the work environment.

Sub-Group 404-03, Roofing & Eavestroughing

Industry Sector 4: Construction

Rate Risk Category	500%

Included	Similar but Classified Elsewhere
✓ Application of roofing materials to the top surface of a building. Includes: • Shingles - can be made of wood (shakes), metal or asphalt. • Rolled roofing • Hot tar or "flat top" roofing - layers of felt and hot asphalt topped with a layer of gravel. Includes incidental sheet metal flashing and construction or replacement of roof decking/sheeting material.	✘ Installation of sheet metal siding is found under 401-04, "Installing Metal Products" ✘ Installation of residential siding is found under 401-02, "Building Construction".
✓ Installation and repair of soffit, fascia, eavestrough and down pipes.	

Last Updated: August 1, 2016

DISCLAIMER: *Industry classification descriptions can change from time to time. Please make sure that you are reading the most current description, which can be found at www.wcb.mb.ca.*