40903 Tower & Energy Construction

PAYROLL

2025 PAYROLL	PAYROLL PERCENTAGE OF CLASSIFICATIONS	2025 REBATE	PROPORTION OF PAYROLL CERTIFIED
$43.4M	2%	$64.1K	63%

SEVERE INJURIES

2023	2024	2025
1	3	0

TIMELOSS INJURIES

2023	2024	2025
48	7	7

RATE RISK CATEGORY

200%

TOP THREE INJURIES

PRIMARY CAUSE OF THE INJURY

1. Fall to floor, walkway
2. Bodily reaction, exertion
3. Overexertion

PRIMARY SOURCE OF THE INJURY

1. Sprains, strains, tears
2. Dislocation
3. Systemic diseases, disorders

NATURE OF THE INJURY

1. Bodily motion or position of worker
2. Viruses
3. Ground

BODY PART INJURED

1. Knees
2. Shoulders
3. Lumber region

CSAM
CONSTRUCTION SAFETY ASSOCIATION OF MANITOBA

40903 Tower & Energy Construction

This classification was once the second largest levied classification primarily involving northern Hydro Projects. The payroll dropped slightly and currently sits at $43.4 M.

In 2025, the classification experienced 7 Time Loss Injuries of which none were of a severe nature. The classification continues to track to a lower Risk Category and may see a re-categorization in the next year to two.

Please refer to the cover page to identify the types of Severe Injuries sustained within the classification over the past 5 years.

Sub-Group 409-03, Tower and Energy Construction

Industry Sector 4: Construction

Rate Risk Category	200%

Included	Similar but Classified Elsewhere
✓ Construction of power lines and replacement of decayed power line poles. Includes incidental clearing of right-of-way for power lines. ✓ Construction and maintenance of power plants, power stations and transformers. ✓ Construction or demolition of windmills. ✓ Erection and maintenance of radio and cellular towers.	✘ Ground line inspection and treatment of power line poles is found under 704-02, "Inspecting & Testing". ✘ The maintenance of wind turbines on a wind farm is found under 605-03, "Heavy Industrial Equipment Sales & Service".
✓ Installation and maintenance of street lights and standards.	✘ Installation of street signs is found under 401-04, Installing Metal Products". ✘ Installation of outdoor decorative/holiday lighting is found under 706-05, "Yard Maintenance & Pest Control"
✓ Construction and maintenance of grain elevators.	✘ Construction of other types of agricultural buildings is found under 401-02, "Building Construction". ✘ Installation of grain bins is found under 406-03, "Installing Heavy Machinery".

Last Updated: August 1, 2016

DISCLAIMER: *Industry classification descriptions can change from time to time. Please make sure that you are reading the most current description, which can be found at www.wcb.mb.ca.*

Sub-Group 409-03, Tower & Energy Construction

Included	Similar but Classified Elsewhere
✓ Work at height, including: • Construction, painting or demolition of church steeples • Erection, repair or demolition of industrial chimneys • Installation of fall arrest systems • Construction of zip lines • Installation of lightning rods	✘ Washing the exterior windows of buildings 706-04, "Window Cleaning".

DISCLAIMER: *Industry classification descriptions can change from time to time. Please make sure that you are reading the most current description, which can be found at www.wcb.mb.ca.*