Safe Work Procedure

Heavy Equipment Operators

Facility:	Written By:	Approved By:	Date Created	Date of Last Revision:

Hazards Present:	PPE or Devices Required:	Additional Training Required:
Other workers and equipment Vehicle damage Slip/Trip Pinch points	Steel toed boots Safety glasses Safety gloves Hard hat	Operator training

Safe Work Procedure:

- 1 Do pre-trip inspection on machine and start using Cold Start Procedure
- 2 Check all gauges and ensure back up alarm are working properly
- 3 When proceeding to the work location, check the brakes
- 4 Turn on beacon light
- 5 While traveling, allow faster traffic to pass if safe to do so
- 6 At job site, inspect area for any hazards
- 7 Always be aware of other workers and equipment in work area
- 8 When parking, park out of way and rest buckets/blades on ground where applicable

If an emergency situation occurs while conducting this task, or there is an equipment malfunction, engage the emergency stop and follow the lock out procedure

REPORT ANY HAZARDOUS SITUATIONS TO YOUR SUPERVISOR

	This Safe Work Procedure will be reviewed any time the task, equipment or materials change and at a
	minimum of every three years
6 Personal Protective Equipment	
16 Machines, Tools and Robots	Reviewed By Worker Rep/WSH Committee:
20 Vehicular and Pedestrian Traffic	
22 Powered Mobile Equipment	
	Date: