

Safe Work Procedure

Jumping Jack Inspection

| | | | | |
|------------------|--------------------|---------------------|---------------------|-------------------------------|
| Facility: | Written By: | Approved By: | Date Created | Date of Last Revision: |
| | | | | |

| Hazards Present: | PPE or Devices Required: | Additional Training Required: |
|--|---|--------------------------------------|
| Eye injuries Hand injuries Noise pollution Pinch points | Steel toed boots Eye protection Hand protection Hearing protection Hard hat | |

| Safe Work Procedure: |
|--|
| <ol style="list-style-type: none"> 1 Check On/Off switch is functioning properly 2 Check rip cord for frays 3 Check air filter 4 Check gas levels 5 Check spark plug 6 Ensure that machine has not been altered in any way before starting 7 Report to supervisor if machine does not meet requirements |

If an emergency situation occurs while conducting this task, or there is an equipment malfunction, engage the emergency stop and follow the lock out procedure

REPORT ANY HAZARDOUS SITUATIONS TO YOUR SUPERVISOR

| | |
|--|--|
| Guidance Documents/Standards: MB Workplace Safety & Health Act & Regulations: 4 General Workplace Requirements 5 First Aid 6 Personal Protective Equipment 16 Machines, Tools and Robots 16.15 Miscellaneous Machines and Tools | This Safe Work Procedure will be reviewed any time the task, equipment or materials change and at a minimum of every three years Reviewed By Worker Rep/WSH Committee: Date: |
|--|--|