

Safe Work Procedure

Quick Cut Saw Inspection

Facility:	Written By:	Approved By:	Date Created	Date of Last Revision:

Hazards Present:	PPE or Devices Required:	Additional Training Required:
Eye injuries Hand injuries Airborne particles Noise pollution	Steel toed boots Eye protection Hand protection Hearing protection Hard hat	

Safe Work Procedure:
<ol style="list-style-type: none"> 1 Check On/Off switch is functioning properly 2 Check rip cord for frays 3 Check air filter 4 Check gas levels 5 Check spark plug 6 Ensure guards are in place and secure 7 Check cutting blades 8 Do check cut ensuring to cut away from body

If an emergency situation occurs while conducting this task, or there is an equipment malfunction, engage the emergency stop and follow the lock out procedure

REPORT ANY HAZARDOUS SITUATIONS TO YOUR SUPERVISOR

Guidance Documents/Standards: MB Workplace Safety & Health Act & Regulations: 4 General Workplace Requirements 5 First Aid 6 Personal Protective Equipment 16 Machines, Tools and Robots 16.15 Miscellaneous Machines and Tools	This Safe Work Procedure will be reviewed any time the task, equipment or materials change and at a minimum of every three years Reviewed By Worker Rep/WSH Committee: Date:
--	--