

40108 – Drywall & Stucco Contracting

PAYROLL

2019 PAYROLL	PAYROLL PERCENTAGE OF CLASSIFICATIONS	2019 REBATE	PROPORTION OF PAYROLL CERTIFIED
\$56.8M	2.86%	\$82K	49%

SEVERE INJURIES

2018	2019	CHANGE
25	22	-5%

TIMELOSS INJURIES

2018	2019	CHANGE
81	64	-21%

RATE RISK CATEGORY

300%

TOP THREE INJURIES

PRIMARY CAUSE OF THE INJURY	PRIMARY SOURCE OF THE INJURY	NATURE OF THE INJURY	BODY PART INJURED
Fall to floor, walkway Bodily reaction, exertion Bending, climbing, crawling	Bodily motion or position of injured worker Wallboard, drywall Floor of building	Sprains, strains, tears Fractures, dislocation Other traumatic injuries & disorders	Shoulders Ankles Knees



40108 DRYWALL & STUCCO CONTRACTING

Drywall & Stucco Contracting is the 6th largest of the 18 classifications currently assigned to CSAM. Payroll of approximately \$57M remained relatively flat when comparing the years 2018 to 2019.

Just under 50% of reported payroll within the classification is COR[®] Certified. This industry classification remains in the 300% Risk Category and currently is not trending in either direction.

While the classification has about 3% of all reported payroll, they currently are responsible for almost 6% of all Severe Injuries which have occurred within the CSAM environment. The classification saw a slight reduction in Severe Injuries 2018=25; 2019=22. In 2019, 55% (12) of the Severe Injuries occurred in a work environment that was NOT safety certified.

Please refer to the coverage page to identify the top 3 drivers of Severe Injuries in the Drywall & Stucco Industry in 2019. Given that Severe Injuries amount to more than 80% of claims costs, they should continue to be the primary focus of any initiatives going forward.

Sub-Group 401-08, Drywall & Stucco Contracting Industry Sector 4: Construction

Rate Risk Category

300%

Included	Similar but Classified Elsewhere
<ul style="list-style-type: none"> ✓ The application of drywall, including taping, sanding, patching/filling. ✓ Repair and application of plaster and lath. ✓ Texturing with plaster (e.g., stipple). 	<ul style="list-style-type: none"> ✗ Framing walls and ceilings is found under 40102, "Building Construction". ✗ Priming and painting is found under 401-05, "Painting & Decorating".
<ul style="list-style-type: none"> ✓ The application of stucco, including incidental installation of stucco paper and wire, and parging. Normally applied to the outside of a building. 	<ul style="list-style-type: none"> ✗ The installation of wood or vinyl siding to the outside of a building is found under 401-02, "Building Construction". ✗ The application of decorative brick to the outside of a building is found under 401-02, "Building Construction".