


40109 – Installing Doors & Windows

PAYROLL



SEVERE INJURIES

2018	2019	CHANGE
3	11	+267%

TIMELOSS INJURIES

2018	2019	CHANGE
18	23	+28%

RATE RISK CATEGORY

300%

TOP THREE INJURIES

PRIMARY CAUSE OF THE INJURY	PRIMARY SOURCE OF THE INJURY	NATURE OF THE INJURY	BODY PART INJURED
Fall to floor, walkway Caught in/compressed by equipment Fall from ladder	Windows Doors Glass window panes	Open wounds Sprains, strains, tears Fracture, dislocation	Shoulders Ankles Knees



40109 INSTALLING DOORS & WINDOWS

This Classification is quite small with payroll in 2019 just short of \$18M representing less than 1% of overall payroll.

It currently sits in the 300% Risk Category and has shown signs of trending towards the 250% category. However, in 2019 there has been a significant spike of Severe Injuries (11) compared to the previous year (3). Payroll remained flat over this time period.

Of the 11 Severe Injuries, 91% (10) occurred in a work environment that was NOT safety certified. Where 37% of the Classification is COR® Certified.

It is not clear what caused the spike of activity. We do note however, that year to-date 2020 Severe Injuries have returned closer to the previous norm of (4) for the year.

At first glance it would appear many of the injuries relate to fingers, wrists and arms.

Please refer to the cover page to identify the applicable drivers.

Sub-Group 401-09, Installing Doors & Windows Industry Sector 4: Construction

Rate Risk Category

300%

Included	Similar but Classified Elsewhere
<p>✓ Installation of metal and wooden windows.</p> <p>Includes installation of plexi-glass or glass storm windows on the inside of the existing windows.</p>	<p>✗ Auto glass installation is found under 604-02, "Automotive Sales & Repairs".</p> <p>✗ Manufacturing windows and doors is found under 314-03, "Manufacturing Doors & Windows".</p>
<p>✓ Replacement/repair of plate glass on-site in installed windows or doors.</p>	<p>✗ Repairing glass in windows and doors where they are not installed (i.e., in a shop setting) is found under 315-17, "Manufacturing Dental, Medical, Jewellery, Glass & Ceramic Products".</p>
<p>✓ Installation of interior and exterior doors and door frames.</p>	<p>✗ Installation of closet doors and shower doors is found under 401-12, "Installing Case Goods & Fixtures".</p> <p>✗ Installation of overhead doors is found under 401-04, "Installing Metal Products".</p>

Last Updated: January 1, 2016

DISCLAIMER: Industry classification descriptions can change from time to time. Please make sure that you are reading the most current description, which can be found at www.wcb.mb.ca.