

# 40103 – Flooring and Tiling

## PAYROLL

2021 PAYROLL

\$41.4M

PAYROLL PERCENTAGE  
OF CLASSIFICATIONS

1.6%

2020 REBATE

\$49K

PROPORTION OF  
PAYROLL CERTIFIED

29%

## SEVERE INJURIES

2019

7

2020

16

2021

8

## TIMELOSS INJURIES

2019

24

2020

33

2021

26

## RATE RISK CATEGORY

150%

## TOP THREE INJURIES

### PRIMARY CAUSE OF THE INJURY

Overexertion in lifting  
Struck by object  
Bending, crawling, climbing

### PRIMARY SOURCE OF THE INJURY

Bodily motion or position of  
injured worker  
Boxes, crates, cartons  
Table saw

### NATURE OF THE INJURY

Sprains, strains, tears  
Fractures, dislocations  
Open wounds

### BODY PART INJURED

Lumbar region  
Knees  
Fingers



## 40103 FLOORING AND TILING

This Classification saw modest payroll growth in 2021. It also saw its Severe Injury ratio return to a more common range given its spike in 2020 to 16. In 2021, the Classification had 8 Severe Injuries and 26 Time Loss Injuries. Of the 8 Severe Injuries (4) took place in a safety certified work environment.

This classification recently incurred a Rate Risk Category increase to 150% and if current claims costs trends continue it can anticipate a further increase within a couple of years. The increase will effect the vast majority of employers within the classification.

Please refer to the cover page to identify the top (3) drivers of Severe Injuries in the Flooring & Tiling Industry over the past 5 years.

## Sub-Group 401-03, Flooring & Tiling Industry Sector 4: Construction

Rate Risk Category

150%

Included	Similar but Classified Elsewhere
<p>✓ Installation and repair of flooring materials, including:</p> <ul style="list-style-type: none"> <li>• Hardwoods</li> <li>• Cork</li> <li>• Laminate</li> <li>• Linoleum</li> <li>• Vinyl sheet goods or tile</li> <li>• Ceramic or stone tile</li> <li>• Terrazzo</li> <li>• Carpet</li> </ul> <p>Includes sanding and refinishing existing or new hardwood flooring.</p>	<p>✗ Retail sales of flooring is found under 601-05, "Department Stores".</p> <p>✗ Pouring concrete floors in basements if found under 401-10, "Concrete Work".</p> <p>✗ Carpentry, masonry and general contracting are found under 401-02, "Building Construction".</p>
<p>✓ Tile-setting - the installation of ceramic, mosaic, quarry, marble or granite tiles on any surface, including the application of grout.</p>	<p>✗ Bricklaying is found under 401-02, "Building Construction".</p>
<p>✓ The installation of acoustic ceiling tile, suspended on a track or applied directly to the ceiling.</p>	<p>✗ Installing drywall to a ceiling is found under 401-08, "Drywall &amp; Stucco Contracting".</p>
<p>✓ All resurfacing (leveling, removing prior coated surface), polishing and finishing of cement floors. Includes resurfacing through the use of any mechanical equipment or chemical means.</p>	<p>Cutting or repairing below the surface of the cement floor is found under 401-10, "Concrete Work".</p>