

# 40103 – Flooring and Tiling

## PAYROLL

2022 PAYROLL

\$40.7M

PAYROLL PERCENTAGE  
OF CLASSIFICATIONS

3%

2022 REBATE

\$36.3K

PROPORTION OF  
PAYROLL CERTIFIED

31%

## SEVERE INJURIES

2020

16

2021

8

2022

5

## TIMELOSS INJURIES

2020

33

2021

26

2022

24

## RATE RISK CATEGORY

150%

## TOP THREE INJURIES

### PRIMARY CAUSE OF THE INJURY

Overexertion in lifting  
Struck by object  
Bending, crawling, climbing

### PRIMARY SOURCE OF THE INJURY

Bodily motion or position of  
injured worker  
Boxes, crates, cartons  
Table saw

### NATURE OF THE INJURY

Sprains, strains, tears  
Fractures, dislocations  
Open wounds

### BODY PART INJURED

Lumbar region  
Knees  
Fingers



## 40103 FLOORING AND TILING

This classification is the 10th largest of the (17) levied Classifications assigned to CSAM. Its 2022 Actual Payroll dropped slightly from 2021 and is currently \$40.7M. Approximately 31% of this payroll is safety certified.

There were a total of (5) Severe Injuries within the classification in 2022 down from (8) from the year before. Four of the injuries took place in a non-certified work environment. Employers within this group paid approximately \$606.4k in premium and certified employers enjoyed a rebate of approximately \$36.3k.

This classification is currently in the 150% Risk Category however recent claims cost analysis suggests costs are more reflective of the 200% Risk Category.

Please refer to the cover page to identify the top (3) drivers of Severe Injuries in the Flooring & Tiling Industry over the past 5 years.

## Sub-Group 401-03, Flooring & Tiling Industry Sector 4: Construction

Rate Risk Category

150%

Included	Similar but Classified Elsewhere
<p>✓ Installation and repair of flooring materials, including:</p> <ul style="list-style-type: none"> <li>• Hardwoods</li> <li>• Cork</li> <li>• Laminate</li> <li>• Linoleum</li> <li>• Vinyl sheet goods or tile</li> <li>• Ceramic or stone tile</li> <li>• Terrazzo</li> <li>• Carpet</li> </ul> <p>Includes sanding and refinishing existing or new hardwood flooring.</p>	<p>✗ Retail sales of flooring is found under 601-05, "Department Stores".</p> <p>✗ Pouring concrete floors in basements if found under 401-10, "Concrete Work".</p> <p>✗ Carpentry, masonry and general contracting are found under 401-02, "Building Construction".</p>
<p>✓ Tile-setting - the installation of ceramic, mosaic, quarry, marble or granite tiles on any surface, including the application of grout.</p>	<p>✗ Bricklaying is found under 401-02, "Building Construction".</p>
<p>✓ The installation of acoustic ceiling tile, suspended on a track or applied directly to the ceiling.</p>	<p>✗ Installing drywall to a ceiling is found under 401-08, "Drywall &amp; Stucco Contracting".</p>
<p>✓ All resurfacing (leveling, removing prior coated surface), polishing and finishing of cement floors. Includes resurfacing through the use of any mechanical equipment or chemical means.</p>	<p>Cutting or repairing below the surface of the cement floor is found under 401-10, "Concrete Work".</p>

Last Updated : January 4, 2022

**DISCLAIMER:** Industry classification descriptions can change from time to time. Please make sure that you are reading the most current description, which can be found at [www.wcb.mb.ca](http://www.wcb.mb.ca).