



# 40109 – Installing Doors and Windows


## PAYROLL




## SEVERE INJURIES




## TIMELOSS INJURIES



## RATE RISK CATEGORY



## TOP THREE INJURIES



## 40109 INSTALLING DOORS AND WINDOWS

This classification is quite small representing just over 1% of levied Actual Payroll assigned to CSAM. Actual Payroll did increase by 7% (\$25.4M) compared to the previous year. Approximately 31% of the payroll is safety certified.

There was a total of (3) Severe Injuries reported in 2022, down from (7) the year before. One of these injuries took place in a safety certified work environment. This classification continues its trend of incurring claims costs in the 300% Risk Category.

Please refer to the cover page to identify the applicable drivers of the Severe Injuries over the past (5) years.

## Sub-Group 401-09, Installing Doors & Windows Industry Sector 4: Construction

Rate Risk Category

300%

Included	Similar but Classified Elsewhere
<p>✓ Installation of metal and wooden windows.</p> <p>Includes installation of plexi-glass or glass storm windows on the inside of the existing windows.</p>	<p>✗ Auto glass installation is found under 604-02, "Automotive Sales &amp; Repairs".</p> <p>✗ Manufacturing windows and doors is found under 314-03, "Manufacturing Doors &amp; Windows".</p>
<p>✓ Replacement/repair of plate glass on-site in installed windows or doors.</p>	<p>✗ Repairing glass in windows and doors where they are not installed (i.e., in a shop setting) is found under 315-17, "Manufacturing Dental, Medical, Jewellery, Glass &amp; Ceramic Products".</p>
<p>✓ Installation of interior and exterior doors and door frames.</p>	<p>✗ Installation of closet doors and shower doors is found under 401-12, "Installing Case Goods &amp; Fixtures".</p> <p>✗ Installation of overhead doors is found under 401-04, "Installing Metal Products".</p>

Last Updated: January 1, 2016

**DISCLAIMER:** Industry classification descriptions can change from time to time. Please make sure that you are reading the most current description, which can be found at [www.wcb.mb.ca](http://www.wcb.mb.ca).