

40103 Flooring & Tiling

PAYROLL

2023 PAYROLL

\$44.4M

PAYROLL PERCENTAGE
OF CLASSIFICATIONS

2%

2023 REBATE

\$33.3K

PROPORTION OF
PAYROLL CERTIFIED

25%

SEVERE INJURIES

2021 | 2022 | 2023

8 | 5 | 9

TIMELOSS INJURIES

2021 | 2022 | 2023

26 | 24 | 20

RATE RISK CATEGORY

150%

TOP THREE INJURIES

PRIMARY CAUSE OF THE INJURY

1. Overexertion in lifting
2. Struck by object
3. Bending, crawling, climbing

PRIMARY SOURCE OF THE INJURY

1. Bodily motion or position of worker
2. Boxes, crates, cartons
3. Table saw

NATURE OF THE INJURY

1. Sprains, strains, tears
2. Fractures, dislocations
3. Open wounds

BODY PART INJURED

1. Lumbar region
2. Knees
3. Fingers

constructionsafety.ca



CSAM
CONSTRUCTION SAFETY
ASSOCIATION OF MANITOBA

40103 Flooring & Tiling

This classification is the 10th largest of the (18) levied Classifications assigned to CSAM. It's 2023 Actual Payroll reported at \$44.4M is up 9% from the previous year. Payroll certification of this payroll stands at 25%.

There were a total of (9) Severe Injuries within the classification in 2023 up from (5) the previous year. Time Loss injuries were down from (24) in 2022 to (20) in 2023.

This classification is currently in the 150% Risk Category however, has consistently shown claims costs more reflective of the 200% Risk Category. The vast majority of the approximate 400 employers within this classification will see a rate increase in the immediate future.

Please refer to the cover page to identify the top (3) drivers of Severe Injuries in the Flooring & Tiling Industry over the past (5) years.

Sub-Group 401-03, Flooring & Tiling Industry Sector 4: Construction

Rate Risk Category

150%

| Included | Similar but Classified Elsewhere |
|---|--|
| <p>✓ Installation and repair of flooring materials, including:</p> <ul style="list-style-type: none"> • Hardwoods • Cork • Laminate • Linoleum • Vinyl sheet goods or tile • Ceramic or stone tile • Terrazzo • Carpet <p>Includes sanding and refinishing existing or new hardwood flooring.</p> | <p>✗ Retail sales of flooring is found under 601-05, "Department Stores".</p> <p>✗ Pouring concrete floors in basements if found under 401-10, "Concrete Work".</p> <p>✗ Carpentry, masonry and general contracting are found under 401-02, "Building Construction".</p> |
| <p>✓ Tile-setting - the installation of ceramic, mosaic, quarry, marble or granite tiles on any surface, including the application of grout.</p> | <p>✗ Bricklaying is found under 401-02, "Building Construction".</p> |
| <p>✓ The installation of acoustic ceiling tile, suspended on a track or applied directly to the ceiling.</p> | <p>✗ Installing drywall to a ceiling is found under 401-08, "Drywall & Stucco Contracting".</p> |
| <p>✓ All resurfacing (leveling, removing prior coated surface), polishing and finishing of cement floors. Includes resurfacing through the use of any mechanical equipment or chemical means.</p> | <p>Cutting or repairing below the surface of the cement floor is found under 401-10, "Concrete Work".</p> |

Last Updated : January 4, 2022

DISCLAIMER: Industry classification descriptions can change from time to time. Please make sure that you are reading the most current description, which can be found at www.wcb.mb.ca.