

40109 Installing Doors & Windows

PAYROLL

2023 PAYROLL

\$26.5M

PAYROLL PERCENTAGE
OF CLASSIFICATIONS

>1%

2023 REBATE

\$12.3K

PROPORTION OF
PAYROLL CERTIFIED

25%

SEVERE INJURIES

2021 | 2022 | 2023

7 | 3 | 7

TIMELOSS INJURIES

2021 | 2022 | 2023

22 | 17 | 17

RATE RISK CATEGORY

300%

TOP THREE INJURIES

PRIMARY CAUSE OF THE INJURY

1. Contact with objects, equipment
2. Fall from ladder
3. Caught in / compressed by equipment

PRIMARY SOURCE OF THE INJURY

1. Open wounds
2. Sprains, strains, tears
3. Dislocation

NATURE OF THE INJURY

1. Windows
2. Bodily motion, position
3. Glass window panes

BODY PART INJURED

1. Fingers
2. Ankles
3. Thumbs

[constructionsafety.ca](https://www.constructionsafety.ca)



CSAM
CONSTRUCTION SAFETY
ASSOCIATION OF MANITOBA

40109 Installing Doors & Windows

This classification is quite small representing just over 1% of total levied payroll. Actual Payroll increased by approximately 4% in 2023 to \$26.5M. Approximately 25% of this payroll is certified.

There were a total of (7) Severe Injuries in 2023 up significantly from the year before (3). Time Loss Injuries remained the same at (17). This classification has incurred claims costs in the 300% Risk Category for numerous years although just recently identified costs in the 250% Category.

Please refer to the cover page to identify the applicable drivers of Severe Injuries over the past (5) years.

Sub-Group 401-09, Installing Doors & Windows Industry Sector 4: Construction

Rate Risk Category

300%

Included	Similar but Classified Elsewhere
<p>✓ Installation of metal and wooden windows.</p> <p>Includes installation of plexi-glass or glass storm windows on the inside of the existing windows.</p>	<p>✗ Auto glass installation is found under 604-02, "Automotive Sales & Repairs".</p> <p>✗ Manufacturing windows and doors is found under 314-03, "Manufacturing Doors & Windows".</p>
<p>✓ Replacement/repair of plate glass on-site in installed windows or doors.</p>	<p>✗ Repairing glass in windows and doors where they are not installed (i.e., in a shop setting) is found under 315-17, "Manufacturing Dental, Medical, Jewellery, Glass & Ceramic Products".</p>
<p>✓ Installation of interior and exterior doors and door frames.</p>	<p>✗ Installation of closet doors and shower doors is found under 401-12, "Installing Case Goods & Fixtures".</p> <p>✗ Installation of overhead doors is found under 401-04, "Installing Metal Products".</p>

Last Updated: January 1, 2016

DISCLAIMER: Industry classification descriptions can change from time to time. Please make sure that you are reading the most current description, which can be found at www.wcb.mb.ca.