

# 40204 Plumbing, Insulating & Mechanical

## PAYROLL

2023 PAYROLL

**\$454.5M**

PAYROLL PERCENTAGE  
OF CLASSIFICATIONS

**23%**

2023 REBATE

**\$830.8K**

PROPORTION OF  
PAYROLL CERTIFIED

**67%**

## SEVERE INJURIES

2021 | 2022 | 2023

**59 | 52 | 67**

## TIMELOSS INJURIES

2021 | 2022 | 2023

**227 | 227 | 242**

## RATE RISK CATEGORY

**200%**

## TOP THREE INJURIES

### PRIMARY CAUSE OF THE INJURY

1. Fall to floor / walkway
2. Fall from ladder
3. Bodily reaction, exertion

### PRIMARY SOURCE OF THE INJURY

1. Sprains, strains, tears
2. Dislocations
3. Open wounds

### NATURE OF THE INJURY

1. Bodily motion / position
2. Floors, walkways
3. Ground

### BODY PART INJURED

1. Shoulders
2. Knees
3. Fingers

[constructionsafety.ca](https://www.constructionsafety.ca)



**CSAM**  
CONSTRUCTION SAFETY  
ASSOCIATION OF MANITOBA

# 40204 Plumbing, Insulating & Mechanical

This classification remains the second largest of the levied classifications at \$454.5M in 2023. This represents an additional \$38M in payroll or a 9% increase. Approximately 67% of this payroll is safety certified.

The classification sustained an increase in both Severe Injuries and Time Loss Injuries. Severe Injuries increased to (67) from the previous years total of (52). Time Loss Injuries increased from (227) to (242).

The classification continues to incur costs within the 200% Risk Category.

Please refer to the cover page to identify the top (3) drivers of Severe Injuries in the classification.

## Sub-Group 402-04, Plumbing, Insulating & Mechanical Industry Sector 4: Construction

Rate Risk Category

200%

Included	Similar but Classified Elsewhere
<p>✓ Installation and on-site repair of residential or commercial plumbing pipes, fixtures or appliances, including:</p> <ul style="list-style-type: none"> <li>• Hot water tanks</li> <li>• Water softeners</li> <li>• Garbage disposal units</li> <li>• Water pumps</li> <li>• Water filters</li> <li>• Indoor automatic sprinkler systems</li> <li>• Cleaning plugged drains and sewer lines</li> </ul>	<ul style="list-style-type: none"> <li>✗ Repair and reconditioning appliances in a shop setting is found under 316-09, "Manufacturing Equipment &amp; Appliances".</li> <li>✗ Installation, repair and servicing of underground automatic water sprinkler systems is found under 401-15, "Landscaping".</li> </ul>
<p>✓ Installation and on-site repair of mechanical (HVAC) components, including:</p> <ul style="list-style-type: none"> <li>• Repair and servicing of boilers.</li> <li>• Furnaces</li> <li>• Central air conditioning systems</li> <li>• Ground-source heating and cooling systems</li> <li>• Refrigeration systems</li> <li>• Exhaust systems</li> <li>• Solar heating systems</li> <li>• Cleaning heating ducts and ventilation pipes, chimneys, furnaces and fireplaces.</li> </ul> <p>Includes work performed by steam fitters and gas fitters, and any incidental drilling or trenching required.</p>	<ul style="list-style-type: none"> <li>✗ The installation of boilers is found under 406-03, "Installing Heavy Machinery".</li> <li>✗ The repair and servicing of window air conditioning units in a shop setting is found under 316-09, "Manufacturing Equipment &amp; Appliances".</li> <li>✗ Custom trenching is found under 408-02, "Trenching &amp; Drainage".</li> <li>✗ Custom drilling for ground source heating systems is found under 202-03 "Drilling, Quarries &amp; Peat Moss".</li> <li>✗ The servicing/maintenance of wind turbines is found under 605-03, "Heavy Industrial Equipment Sales &amp; Service".</li> </ul>

Last Updated: August 1, 2016

**DISCLAIMER:** Industry classification descriptions can change from time to time. Please make sure that you are reading the most current description, which can be found at [www.wcb.mb.ca](http://www.wcb.mb.ca).

## Sub-Group 402-04, Plumbing, Insulating & Mechanical Page 2 of 2

Included	Similar but Classified Elsewhere
<p>✓ Installation and removal of fiberglass, rigid foam and spray-on insulation in buildings or for on-site equipment. Includes asbestos remediation.</p> <p>Includes installation of weather-stripping, caulking and vapour barriers.</p> <p>Spray-on insulation systems can also include fireproofing, soundproofing, air sealing or another specialty coating.</p>	<p>✗ Repair and reconditioning vacuum cleaners in a shop setting is found under 316-09, "Manufacturing Equipment &amp; Appliances".</p>
<p>✓ Installation and on-site repair of built-in ("central") vacuum systems.</p>	

Last Updated: August 1, 2016

**DISCLAIMER:** Industry classification descriptions can change from time to time. Please make sure that you are reading the most current description, which can be found at [www.wcb.mb.ca](http://www.wcb.mb.ca).