

40103 Flooring & Tiling

PAYROLL

2024 PAYROLL

\$45.3M

PAYROLL PERCENTAGE
OF CLASSIFICATIONS

2%

2024 REBATE

\$32.2K

PROPORTION OF
PAYROLL CERTIFIED

25%

SEVERE INJURIES

2022	2023	2024
5	9	8

TIMELOSS INJURIES

2022	2023	2024
24	20	18

RATE RISK CATEGORY

150%

TOP THREE INJURIES

PRIMARY CAUSE OF THE INJURY

1. Overexertion in lifting
2. Struck by object
3. Bending, crawling, climbing

PRIMARY SOURCE OF THE INJURY

1. Bodily motion or position of worker
2. Boxes, crates, cartons
3. Table saw

NATURE OF THE INJURY

1. Sprains, strains, tears
2. Fractures, dislocations
3. Open wounds

BODY PART INJURED

1. Lumbar region
2. Knees
3. Fingers

constructionSafety.ca

40103 Flooring & Tiling

This classification saw minor payroll growth in 2024 of about (2%) or currently \$45.3M. Approximately (25%) of this payroll is safety certified.

Severe Injuries dropped by (1) from the previous year and Time Loss Injuries dropped from (20) to (18).

The Risk Category had been trending towards 200%, however, remains in the 150% Risk Category and is no longer trending.

Please refer to the cover page to identify the top (3) drivers of Severe Injuries in the Flooring & Tiling Industry over the past (5) years.

constructionSafety.ca



Sub-Group 401-03, Flooring & Tiling Industry Sector 4: Construction

Rate Risk Category	150%
--------------------	------

Included	Similar but Classified Elsewhere
<ul style="list-style-type: none"> ✓ Installation and repair of flooring materials, including: <ul style="list-style-type: none"> • Hardwoods • Cork • Laminate • Linoleum • Vinyl sheet goods or tile • Ceramic or stone tile • Terrazzo • Carpet <p>Includes sanding and refinishing existing or new hardwood flooring.</p>	<ul style="list-style-type: none"> ✗ Retail sales of flooring is found under 601-05, "Department Stores". ✗ Pouring concrete floors in basements if found under 401-10, "Concrete Work". ✗ Carpentry, masonry and general contracting are found under 401-02, "Building Construction".
<ul style="list-style-type: none"> ✓ Tile-setting - the installation of ceramic, mosaic, quarry, marble or granite tiles on any surface, including the application of grout. 	<ul style="list-style-type: none"> ✗ Bricklaying is found under 401-02, "Building Construction".
<ul style="list-style-type: none"> ✓ The installation of acoustic ceiling tile, suspended on a track or applied directly to the ceiling. 	<ul style="list-style-type: none"> ✗ Installing drywall to a ceiling is found under 401-08, "Drywall & Stucco Contracting".
<ul style="list-style-type: none"> ✓ All resurfacing (leveling, removing prior coated surface), polishing and finishing of cement floors. Includes resurfacing through the use of any mechanical equipment or chemical means. 	<p>Cutting or repairing below the surface of the cement floor is found under 401-10, "Concrete Work".</p>

Last Updated : January 4, 2022

DISCLAIMER: Industry classification descriptions can change from time to time. Please make sure that you are reading the most current description, which can be found at www.wcb.mb.ca.