

40109 Installing Doors & Windows

PAYROLL

2024 PAYROLL	PAYROLL PERCENTAGE OF CLASSIFICATIONS	2024 REBATE	PROPORTION OF PAYROLL CERTIFIED
\$25.7M	>1%	\$13K	28%

SEVERE INJURIES	TIMELOSS INJURIES	RATE RISK CATEGORY												
<table><tr><td>2022</td><td>2023</td><td>2024</td></tr><tr><td>3</td><td>7</td><td>5</td></tr></table>	2022	2023	2024	3	7	5	<table><tr><td>2022</td><td>2023</td><td>2024</td></tr><tr><td>17</td><td>17</td><td>18</td></tr></table>	2022	2023	2024	17	17	18	300%
2022	2023	2024												
3	7	5												
2022	2023	2024												
17	17	18												

TOP THREE INJURIES

PRIMARY CAUSE OF THE INJURY	PRIMARY SOURCE OF THE INJURY	NATURE OF THE INJURY	BODY PART INJURED
<ol style="list-style-type: none">Contact with objects, equipmentFall from ladderCaught in / compressed by equipment	<ol style="list-style-type: none">Open woundsSprains, strains, tearsDislocation	<ol style="list-style-type: none">WindowsBodily motion, positionGlass window panes	<ol style="list-style-type: none">FingersAnklesThumbs

40109 Installing Doors & Windows

This classification is quite small and saw a slight decline in Actual Payroll over the past year \$26.5M to \$25.7M . Approximately 28% of the payroll is safety certified.

The classification sustained 5 Severe Injuries in 2024 all of which took place in a non safety certified work environments.

This classification continues to show improvement in lowering claims costs. It currently resides in the 300% Risk Category. If this trend continues it will be reclassified to the 250% Risk Category.

Please refer to the cover page to identify the applicable drivers of Severe Injuries over the past 5 years.

Sub-Group 401-09, Installing Doors & Windows Industry Sector 4: Construction

Rate Risk Category

300%

Included	Similar but Classified Elsewhere
<p>✓ Installation of metal and wooden windows.</p> <p>Includes installation of plexi-glass or glass storm windows on the inside of the existing windows.</p>	<p>✗ Auto glass installation is found under 604-02, "Automotive Sales & Repairs".</p> <p>✗ Manufacturing windows and doors is found under 314-03, "Manufacturing Doors & Windows".</p>
<p>✓ Replacement/repair of plate glass on-site in installed windows or doors.</p>	<p>✗ Repairing glass in windows and doors where they are not installed (i.e., in a shop setting) is found under 315-17, "Manufacturing Dental, Medical, Jewellery, Glass & Ceramic Products".</p>
<p>✓ Installation of interior and exterior doors and door frames.</p>	<p>✗ Installation of closet doors and shower doors is found under 401-12, "Installing Case Goods & Fixtures".</p> <p>✗ Installation of overhead doors is found under 401-04, "Installing Metal Products".</p>

Last Updated: January 1, 2016

DISCLAIMER: Industry classification descriptions can change from time to time. Please make sure that you are reading the most current description, which can be found at www.wcb.mb.ca.