

Safe Work Procedures

Housekeeping

Identified hazards: Falls, sprains, cuts & bruises

Required PPE: Safety footwear, hard hat, gloves,

1. Prior to starting work, check the work area to ensure there are no risks that are evident.
2. Clear walkways, entrances and exits of debris or hazards as practicable.
3. Place tools and equipment in a safe place when not in use.
4. Clean up any hazardous spills as quickly as practicable.
5. Make sure the job site is cleaned up before leaving the site.
6. Keep lunch areas clean.
7. Follow safe work practices at all times.