

Safe Work Procedure

Rock Truck Operator

Facility:	Written By:	Approved By:	Date Created	Date of Last Revision:

Hazards Present:	PPE or Devices Required:	Additional Training Required:
Pinch points Slip/Trip Vehicle damage/malfunction	Steel toed Eye protection Hand protection Hard hat	Operator Certification

Safe Work Procedure:
<ol style="list-style-type: none">1 Perform pre trip inspection on rock truck2 Inspect work area for any potential hazards3 Pull up as close as possible to loading area, if backing up use a spotter4 Wait for signal that truck is full then proceed to dump area5 Dump slowly and cautiously

If an emergency situation occurs while conducting this task, or there is an equipment malfunction, engage the emergency stop and follow the lock out procedure

REPORT ANY HAZARDOUS SITUATIONS TO YOUR SUPERVISOR

Guidance Documents/Standards: MB Workplace Safety & Health Act & Regulations: 4 General Workplace Requirements 16 Machines, Tools and Robots 22 Powered Mobile Equipment	This Safe Work Procedure will be reviewed any time the task, equipment or materials change and at a minimum of every three years
	Reviewed By Worker Rep/ WSH Committee: Date: