

Safe Work Procedure/Shingling

Site:	Written By:	Approved By:	Date created:	Date of late revision
Morello	Jared Driedger		March 15, 2008	

Hazards Present:	PPE	Additional Training Required
*Dangerous height *Hoses and possible material drop Possible frost causing slips *Required work on sloped work surface *Tripping Hazard	*Knee pads *Safety boots *Safety glasses *Hearing protection	*Guardrails *Safety harness *Fall restraint equipment

Safe Work Procedures
*Proper orientation for all workers, working on roof *Ensure all PPE in use *Ensure work surface is clear of debris *Beware of other workers either on roof or on ground *Ensure access ladders are properly secured

Guidance Criteria	
*Safework Procedures *Company Rules *Manitoba Workplace Safety and Health Regulations M.R 217/206	This "Safe Work Procedure" must be reviewed and updated as required

All Procedures and relevant manuals, materials and equipment must be reviewed and approved.