



**SAFE JOB PROCEDURES**

<u>JOB</u>	<u>Written by</u>	<u>Approved by</u>	<u>Date</u>
Table saw	K. Thomas	K. Mardynalka	December 6, 2010

<u>Hazards</u>	<u>PPE Required</u>	<u>Additional Training</u>
Cuts, amputation, electric shock, sawdust, noise	Safety glasses, hard hat, safety boots, mask	On the job training
<p>Safe Work Procedure:</p> <ol style="list-style-type: none"> <li>1. Ensure that work area is clean and free of debris</li> <li>2. Inspect all equipment and safety features before use of the saw</li> <li>3. Wear all of the required PPE</li> <li>4. Maintain a good position, Feet far enough apart for good balance. Position your body to the left of the blade. Never line up right with the blade.</li> <li>5. Always keep finger 3" away from the blade</li> <li>6. Always use your splitter and guard through all cuts</li> <li>7. Make adjustments only when machine is turn off and de energized</li> <li>8. Never clear small pieces away when blade is moving</li> <li>9. Do not reach over or behind the blade unless the blade is stopped</li> <li>10. Always use the outfeed table when required</li> <li>11. Always ensure to use the proper inserts</li> <li>12. Check the wood / stock for knots, nails or any other debris</li> <li>13. Use a push stick to rip stock that is 3" or less.</li> <li>14. Ensure machine is de energized before cleaning.</li> </ol>		



## SAFE JOB PROCEDURES

Guidance Documents / Standards/ applicable legislation/ other:

Guidance Documents: Operator/owners manual

WSH 210/2006: 2.1,2.3,6.1,6.3,6.4,6.5,6.6,6.7-6.18,  
16.1,16.2,16.3,16.4,16.5,16.6,16.7,16.8,16.9,16.10,16.11,16.13,16.14,16.15,