


# 40204 – Plumbing, Insulating & Mechanical

## PAYROLL



## SEVERE INJURIES

2018	2019	CHANGE
52	43	-17%


## TIMELOSS INJURIES

2018	2019	CHANGE
234	201	-14%

## RATE RISK CATEGORY

200%

## TOP THREE INJURIES



## 40204 PLUMBING, INSULATING & MECHANICAL

Plumbing Insulating and Mechanical saw fairly significant payroll growth when comparing 2018 to 2019, up approximately 10%. The classification now pays annual premiums approaching \$7M and is the second largest classification based on payroll size.

The classification is currently in the 200% Risk Category and maintains a safety certification rate of approximately 62% of its payroll.

From 2018 to 2019 Severe Injuries dropped by over 17% despite the 10% overall growth. Interestingly, the drop occurred in the Severe Injury category involving claims that took place in a non-certified work environment. This may warrant further investigation in an attempt to determine why.

Please refer to the cover page to identify the top (3) drivers of Severe Injuries in the Plumbing Insulating and Mechanical Industry in 2019. Given that Severe Injuries amount to more than 80% of claims costs they should continue to be the primary focus of any initiatives going forward.

## Sub-Group 402-04, Plumbing, Insulating & Mechanical Industry Sector 4: Construction

Rate Risk Category

200%

Included	Similar but Classified Elsewhere
<p>✓ Installation and on-site repair of residential or commercial plumbing pipes, fixtures or appliances, including:</p> <ul style="list-style-type: none"> <li>• Hot water tanks</li> <li>• Water softeners</li> <li>• Garbage disposal units</li> <li>• Water pumps</li> <li>• Water filters</li> <li>• Indoor automatic sprinkler systems</li> <li>• Cleaning plugged drains and sewer lines</li> </ul>	<ul style="list-style-type: none"> <li>✗ Repair and reconditioning appliances in a shop setting is found under 316-09, "Manufacturing Equipment &amp; Appliances".</li> <li>✗ Installation, repair and servicing of underground automatic water sprinkler systems is found under 401-15, "Landscaping".</li> </ul>
<p>✓ Installation and on-site repair of mechanical (HVAC) components, including:</p> <ul style="list-style-type: none"> <li>• Repair and servicing of boilers.</li> <li>• Furnaces</li> <li>• Central air conditioning systems</li> <li>• Ground-source heating and cooling systems</li> <li>• Refrigeration systems</li> <li>• Exhaust systems</li> <li>• Solar heating systems</li> <li>• Cleaning heating ducts and ventilation pipes, chimneys, furnaces and fireplaces.</li> </ul> <p>Includes work performed by steam fitters and gas fitters, and any incidental drilling or trenching required.</p>	<ul style="list-style-type: none"> <li>✗ The installation of boilers is found under 406-03, "Installing Heavy Machinery".</li> <li>✗ The repair and servicing of window air conditioning units in a shop setting is found under 316-09, "Manufacturing Equipment &amp; Appliances".</li> <li>✗ Custom trenching is found under 408-02, "Trenching &amp; Drainage".</li> <li>✗ Custom drilling for ground source heating systems is found under 202-03 "Drilling, Quarries &amp; Peat Moss".</li> <li>✗ The servicing/maintenance of wind turbines is found under 605-03, "Heavy Industrial Equipment Sales &amp; Service".</li> </ul>

Last Updated: August 1, 2016

**DISCLAIMER:** Industry classification descriptions can change from time to time. Please make sure that you are reading the most current description, which can be found at [www.wcb.mb.ca](http://www.wcb.mb.ca).

## Sub-Group 402-04, Plumbing, Insulating & Mechanical Page 2 of 2

Included	Similar but Classified Elsewhere
<p>✓ Installation and removal of fiberglass, rigid foam and spray-on insulation in buildings or for on-site equipment. Includes asbestos remediation.</p> <p>Includes installation of weather-stripping, caulking and vapour barriers.</p> <p>Spray-on insulation systems can also include fireproofing, soundproofing, air sealing or another specialty coating.</p>	<p>✗ Repair and reconditioning vacuum cleaners in a shop setting is found under 316-09, "Manufacturing Equipment &amp; Appliances".</p>
<p>✓ Installation and on-site repair of built-in ("central") vacuum systems.</p>	

Last Updated: August 1, 2016

**DISCLAIMER:** Industry classification descriptions can change from time to time. Please make sure that you are reading the most current description, which can be found at [www.wcb.mb.ca](http://www.wcb.mb.ca).