



# 40108 – Drywall and Stucco Contracting


## PAYROLL




## SEVERE INJURIES




## TIMELOSS INJURIES



## RATE RISK CATEGORY



## TOP THREE INJURIES



## 40108 DRYWALL AND STUCCO CONTRACTING

This classification saw significant growth this past year despite the pandemic. Payroll grew from approximately \$57M to \$62M. The classification remains the 6th largest levied classification and represents 3.32% of all levied payroll.

It continues to reside and experience claims costs in the 300% Risk Category. Approximately 46% of this payroll is safety certified. Safety certified employers received \$157k of returned premium by way of rebate.

Despite its growth, it saw a dramatic decrease in Severe Injuries (13) compared to (22) the previous year.

Please refer to the cover page to identify the top (3) drivers of Severe Injuries. This data is based on a 5 year history of claims.

While the classification has about 3% of all reported payroll, they currently are responsible for almost 6% of all Severe Injuries which have occurred within the CSAM environment. The classification saw a slight reduction in Severe Injuries 2018=25; 2019=22. In 2019, 10 of the Severe Injuries happened within a COR<sup>®</sup> certified environment.

Please refer to the coverage page to identify the top (3) drivers of Severe Injuries in the Drywall and Stucco Industry in 2019. Given that Severe Injuries amount to more than 80% of claims costs, they should continue to be the primary focus of any initiatives going forward.

## Sub-Group 401-08, Drywall & Stucco Contracting Industry Sector 4: Construction

Rate Risk Category

300%

| Included   | Similar but Classified Elsewhere  |
|--|---|
| <ul style="list-style-type: none"> <li>✓ The application of drywall, including taping, sanding, patching/filling.</li> <li>✓ Repair and application of plaster and lath.</li> <li>✓ Texturing with plaster (e.g., stipple).</li> </ul> | <ul style="list-style-type: none"> <li>✗ Framing walls and ceilings is found under 40102, "Building Construction".</li> <li>✗ Priming and painting is found under 401-05, "Painting &amp; Decorating".</li> </ul>   |
| <ul style="list-style-type: none"> <li>✓ The application of stucco, including incidental installation of stucco paper and wire, and parging. Normally applied to the outside of a building.</li> </ul>                                 | <ul style="list-style-type: none"> <li>✗ The installation of wood or vinyl siding to the outside of a building is found under 401-02, "Building Construction".</li> <li>✗ The application of decorative brick to the outside of a building is found under 401-02, "Building Construction".</li> </ul> |