40403 - Roofing and Eavestroughing

PAYROLL

2022 PAYROLL

\$84.3M

PAYROLL PERCENTAGE OF CLASSIFICATIONS

4%

2022 REBATE

\$303K

PROPORTION OF PAYROLL CERTIFIED

74%

SEVERE INJURIES

2020	2021	2022
32	30	18

TIMELOSS INJURIES

2020	2021	2022
92	82	75

RATE RISK CATEGORY

500%

TOP THREE INJURIES

PRIMARY CAUSE OF THE INJURY

Fall from ladder
fall to floor/walkway
Fall from roof edge

PRIMARY SOURCE OF THE INJURY

Dislocations

Sprains, strains, tears

Open wounds

NATURE OF THE INJURY

Ground

Bodily motion/position

Floors, walkways

BODY PART INJURED

Multiple body parts

Fingers

Knees

constructionsafety.ca



40403 ROOFING AND EAVESTROUGHING

This classification saw an Actual Payroll increase of approximately 7% or \$84.3M of all levied payroll in 2022. A good portion 74% of this payroll is safety certified.

In 2022, there was a significant drop in Severe Injuries from (30) in 2021, to (18) in 2022. (13) of these injuries took place in a safety certified work environment.

Claims costs continue to track at the 500% Risk Category. The Classification represents about 4% of levied payroll, but approximately 6% of Severe Injuries incurred in 2022.

Please refer to the cover page which provides some insight into the causes and types of injuries sustained in this work environment.

constructionsafety.ca





Industry Classifications

Sub-Group 404-03, Roofing & Eavestroughing Industry Sector 4: Construction

Rate Risk Category 500%

Included	Similar but Classified Elsewhere
✓ Application of roofing materials to the top surface of a building. Includes:	
 Shingles - can be made of wood (shakes), metal or asphalt. Rolled roofing Hot tar or "flat top" roofing - layers of felt and hot asphalt topped with a layer of gravel. 	 Installation of sheet metal siding is found under 401-04, "Installing Metal Products" Installation of residential siding is found under 401-02, "Building Construction".
Includes incidental sheet metal flashing and construction or replacement of roof decking/sheeting material.	
✓ Installation and repair of soffit, fascia, eavestrough and down pipes.	

Last Updated: August 1, 2016