

# 40105 Painting & Decorating

## PAYROLL

2023 PAYROLL

**\$62.7M**

PAYROLL PERCENTAGE  
OF CLASSIFICATIONS

**3%**

2023 REBATE

**\$80.9K**

PROPORTION OF  
PAYROLL CERTIFIED

**33%**

## SEVERE INJURIES

2021 | 2022 | 2023

6

16

8

## TIMELOSS INJURIES

2021 | 2022 | 2023

32

38

34

## RATE RISK CATEGORY

**200%**

## TOP THREE INJURIES

### PRIMARY CAUSE OF THE INJURY

1. Fall from ladder
2. Fall to floor, walkway, etc.
3. Bodily reaction, exertion

### PRIMARY SOURCE OF THE INJURY

1. Sprains, strains, tears
2. Dislocations
3. Other traumatic injuries

### NATURE OF THE INJURY

1. Bodily motion, position
2. Floor of building
3. Ground

### BODY PART INJURED

1. Knees
2. Ankles
3. Multiple body parts

[constructionsafety.ca](https://www.constructionsafety.ca)



**CSAM**  
CONSTRUCTION SAFETY  
ASSOCIATION OF MANITOBA

# 40105 Painting & Decorating

In 2023, Painting & Decorating saw an increase in Actual Payroll from \$58.9M to \$62.7 or 6%. Approximately 33% of this payroll is safety certified.

Severe Injuries returned closer to the norm at (8) during 2023, a significant drop from the (16) the previous year. Time Loss Injuries also dropped from (38) to (34). Positive signs given the payroll growth would suggest an increase in overall exposure hours.

This classification continues to incur claims costs within the 200% Risk Category.

Please refer to the cover page to identify the top (3) drivers of Severe Injuries in the classification.

## Sub-Group 401-05, Painting & Decorating Industry Sector 4: Construction

Rate Risk Category

200%

Included	Similar but Classified Elsewhere
<p>✓ Preparation for and application of paint by brush, roller or pressure sprayer to the inside or outside of buildings.</p> <p>Includes the painting of murals, decorative artwork or installation of scenery for backdrops.</p> <p>✓ Hanging wallpaper</p> <p>✓ Preparing or cleaning a surface for paint, or removing old layers of paint, by any of the following processes:</p> <ul style="list-style-type: none"> <li>• Sandblasting</li> <li>• Water blasting/power washing</li> </ul>	<p>✗ Custom finishing of millwork is found under 316-10, "Plating, Engraving, Coating &amp; Manufacturing Paint".</p> <p>✗ Painting vehicles is found under 604-04, "Automotive Body Shops".</p> <p>✗ Painting and manufacturing signs, is found under 311-05, "Fabricating Signs".</p> <p>✗ Painting lines in parking lots and on roadways is found under 408-03, "Roadwork".</p> <p>✗ Painting bridges is found under 405-02, "Constructing Bridges &amp; Steel Buildings".</p> <p>✗ Painting towers, street light standards and gantries, steeples, and, grain elevators, etc., is found under 409-03, "Tower &amp; Energy Construction".</p>
<p>✓ Tinting windows by installing a film on windows inside buildings.</p>	<p>✗ Tinting windows in vehicles is found under class 604-04, "Body Repairs &amp; Paint".</p>
<p>✓ Tub refinishing or resurfacing on-site.</p>	<p>✗ Tub refinishing in a shop setting is found under 316-10, "Plating, Engraving, Coating and Manufacturing Paint".</p>

Last Updated: August 1, 2016

**DISCLAIMER:** Industry classification descriptions can change from time to time. Please make sure that you are reading the most current description, which can be found at [www.wcb.mb.ca](http://www.wcb.mb.ca).