

40903 Tower & Energy Construction

PAYROLL

2023 PAYROLL

\$42.4M

PAYROLL PERCENTAGE
OF CLASSIFICATIONS

2%

2023 REBATE

\$80.51K

PROPORTION OF
PAYROLL CERTIFIED

58%

SEVERE INJURIES

2021 | 2022 | 2023

7

6

1

TIMELOSS INJURIES

2021 | 2022 | 2023

16

49

8

RATE RISK CATEGORY

200%

TOP THREE INJURIES

PRIMARY CAUSE OF THE INJURY

1. Fall to floor, walkway
2. Bodily reaction, exertion
3. Overexertion

PRIMARY SOURCE OF THE INJURY

1. Sprains, strains, tears
2. Dislocation
3. Systemic diseases, disorders

NATURE OF THE INJURY

1. Bodily motion or position of worker
2. Viruses
3. Ground

BODY PART INJURED

1. Knees
2. Shoulders
3. Lumber region

constructionsafety.ca



CSAM
CONSTRUCTION SAFETY
ASSOCIATION OF MANITOBA

40903 Tower & Energy Construction

This classification was once the second largest of levied classifications, however, as Hydro projects wind down it is now one of the smallest classifications. Payroll dropped approximately 33% last year from \$62.4M to \$42.4M. Approximately 58% of this payroll is safety certified.

Severe Injuries are down from (6) in 2022 to (1) in 2023. Time Loss Injuries are also down significantly from (49) to (8).

Claims costs continue to track in the 200% Risk Category.

Please refer to the cover page to identify the types of severe injuries sustained in this classification over the past (5) years.

Sub-Group 409-03, Tower and Energy Construction Industry Sector 4: Construction

Rate Risk Category

200%

Included	Similar but Classified Elsewhere
<ul style="list-style-type: none"> ✓ Construction of power lines and replacement of decayed power line poles. Includes incidental clearing of right-of-way for power lines. ✓ Construction and maintenance of power plants, power stations and transformers. ✓ Construction or demolition of windmills. ✓ Erection and maintenance of radio and cellular towers. 	<ul style="list-style-type: none"> ✗ Ground line inspection and treatment of power line poles is found under 704-02, "Inspecting & Testing". ✗ The maintenance of wind turbines on a wind farm is found under 605-03, "Heavy Industrial Equipment Sales & Service".
<ul style="list-style-type: none"> ✓ Installation and maintenance of street lights and standards. 	<ul style="list-style-type: none"> ✗ Installation of street signs is found under 401-04, "Installing Metal Products". ✗ Installation of outdoor decorative/holiday lighting is found under 706-05, "Yard Maintenance & Pest Control"
<ul style="list-style-type: none"> ✓ Construction and maintenance of grain elevators. 	<ul style="list-style-type: none"> ✗ Construction of other types of agricultural buildings is found under 401-02, "Building Construction". ✗ Installation of grain bins is found under 406-03, "Installing Heavy Machinery".

Last Updated: August 1, 2016

DISCLAIMER: Industry classification descriptions can change from time to time. Please make sure that you are reading the most current description, which can be found at www.wcb.mb.ca.

Included	Similar but Classified Elsewhere
<p>✓ Work at height, including:</p> <ul style="list-style-type: none"> • Construction, painting or demolition of church steeples • Erection, repair or demolition of industrial chimneys • Installation of fall arrest systems • Construction of zip lines • Installation of lightning rods 	<p>✗ Washing the exterior windows of buildings 706-04, "Window Cleaning".</p>