### **40108 - Drywall and Stucco Contracting**

#### **PAYROLL**

**2022 PAYROLL** 

\$68.5M

PAYROLL PERCENTAGE OF CLASSIFICATIONS

4%

**2022 REBATE** 

\$169K

PROPORTION OF PAYROLL CERTIFIED

50%

#### **SEVERE INJURIES**

2020	2021	2022
13	17	16

#### **TIMELOSS INJURIES**

2020	2021	2022
54	77	57

#### RATE RISK CATEGORY

300%

#### **TOP THREE INJURIES**

PRIMARY CAUSE OF THE INJURY

Fall from walkway or other Bending, climbing, crawling Fall from scaffold PRIMARY SOURCE OF THE INJURY

Dislocations

Sprains, strains, tears

Systemic disease disorders

NATURE OF THE INJURY

**Bodily motion** 

Floors, walkways, floor of building

Wallboard, drywall

BODY PART INJURED

Wrists

Ankles

Shoulders

constructionsafety.ca



#### 40108 DRYWALL AND STUCCO CONTRACTING

This classification's Actual Payroll remained relatively flat in 2022, reported at \$68.5M. This amount represents about 4% of all levied payroll assigned to CSAM. It is the 6th largest Classification of the 18 levied classifications. About 50% of this payroll is safety certified.

Severe Injuries (16) are down (1) from the previous year. (9) of these incidents took place in a safety certified work environment. This Classification paid \$2.2M in premium of which \$169k was returned to safety certified companies by rebate. The classification continues a trend of incurring claims costs in the 300% Risk Category.

Please refer to the cover page to identify the top (3) drivers of Severe Injuries. Our primary attention is given to Severe Injuries as they account for approximately 80% of claims costs.

constructionsafety.ca





## **Industry Classifications**

# Sub-Group 401-08, Drywall & Stucco Contracting Industry Sector 4: Construction

Rate Risk Category 300%

Included	Similar but Classified Elsewhere	
✓ The application of drywall, including taping, sanding, patching/filling.	Framing walls and ceilings is found under 40102, "Building Construction".	
<ul> <li>Repair and application of plaster and lath.</li> </ul>	Priming and painting is found under	
✓ Texturing with plaster (e.g., stipple).		
✓ The application of stucco, including incidental installation of stucco paper and wire, and parging. Normally applied to the outside of a building.	<ul> <li>The installation of wood or vinyl siding to the outside of a building is found under 401-02, "Building Construction".</li> <li>The application of decorative brick to the outside of a building is found under 401-02, "Building Construction".</li> </ul>	

Version 1 Effective: January 1, 2014